

# Final Reclamation Inspection

January 17th, 2024

Operator: Williford Resources LLC - 96735

Location ID: 325528

Inspection Document #: 714000319

La Plata County, CO

Township: SESE 1 33N 12W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Angelina 1-D  
Location ID: 325528



1/17/24  
+37.127681,-108.094460  
289° W



1/17/24  
+37.127681,-108.094460  
274° W

Photo 1. View of the disturbance from the entrance facing center.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-06557

Inspection Photos  
Location Name: Angelina 1-D  
Location ID: 325528



**Photo 2.** View of the associated tank battery from the western edge facing east.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-06557

Inspection Photos  
Location Name: Angelina 1-D  
Location ID: 325528



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** View of weedy debris observed around tank battery equipment.

API #: 067-06557

Inspection Photos  
Location Name: Angelina 1-D  
Location ID: 325528



**Photo 4.** View of oily substance spilling from tank battery equipment.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-06557

Inspection Photos  
Location Name: Angelina 1-D  
Location ID: 325528

1/17/24  
+37.127876,-108.094460  
355° N



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Equipment observed in previous inspection doc #695108246 has been removed from location. Interim vegetation was not fully assessed due to snowy conditions.

API #: 067-06557