

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403657744

Date Received:  
01/17/2024

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 714000278

Inspection Date: 12/28/2023

FIR Submit Date: 01/08/2024

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

**LOCATION** - Location ID: 333703

Location Name: DOWING RALPH GAS UNIT-M34N8W Number: 9NESW County: \_\_\_\_\_

Qtrqtr: NESW Sec: 9 Twp: 34N Range: 8W Meridian: M

Latitude: 37.202357 Longitude: -107.726715

**FACILITY** - API Number: 05-067-00 Facility ID: 333703

Facility Name: DOWING RALPH GAS UNIT-M34N8W Number: 9NESW

Qtrqtr: NESW Sec: 9 Twp: 34N Range: 8W Meridian: M

Latitude: 37.202357 Longitude: -107.726715

**CORRECTIVE ACTIONS:**

**1**  CA# 189902

Corrective Action: Comply with rule 606, remove and properly dispose of debris.

Date: 12/28/2023

Response: CA COMPLETED

Date of Completion: 01/16/2024

Operator Comment: Debris removed from location.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Debris CA completed. See attached completion photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Gabby Riley Signed: \_\_\_\_\_

Title: Permitting Specialist I Date: 1/17/2024 3:09:40 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403657744	FIR RESOLUTION SUBMITTED
403657750	Ralph Downing A2 & A4; CA completion photos - debris

Total Attach: 2 Files