

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S96W/25NESW

Location ID: 311649

Date: 1/18/2024



Location Entrance – Photo #08729



Wellheads – Photo #08730

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S96W/25NESW

Location ID: 311649

Date: 1/18/2024



Gas Meters – Photo #08735



Gas Lifts – Photo #08734

Inspection Photos


Location Name: CAERUS PICEANCE LLC, N.PARACHUTE-65S96W/25NESW

Location ID: 311649

Date: 1/18/2024



Tank Battery – Photo #08731



Chem Tanks – Photo #08733