

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S96W/25NESW

Location ID: 335649

Date: 1/18/2024



Location Entrance – Photo #08737



Wellheads – Photo #08739

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S96W/25NESW

Location ID: 335649

Date: 1/18/2024



Gas Meter/Chem Tank – Photo #08738



Gas Lift/Chem Tank – Photo #08740