

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/19LOT 2

Location ID: 335901

Date: 1/18/2024



Location Entrance – Photo #08765



Wellheads – Photo #08769

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/19LOT 2

Location ID: 335901

Date: 1/18/2024



Gas Meters – Photo #08771



Gas Lifts – Photo #08767

Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/19LOT 2

Location ID: 335901

Date: 1/18/2024



Tank Battery – Photo #08768



Mobile Separators – Photo #08773