

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/19LOT 2

Location ID: 335901

Date: 1/18/2024



Location Entrance – Photo #08775



Wellheads – Photo #08776

## Inspection Photos


Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/19LOT 2

Location ID: 335901

Date: 1/18/2024



Gas Meters – Photo #08779



Gas Lifts – Photo #08777



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/19LOT 2

Location ID: 335901

Date: 1/18/2024



Chemical Tanks – Photo #08778



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources