

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/18/2024

Submitted Date:

01/21/2024

Document Number:

708301560

**FIELD INSPECTION FORM**

|  |                                    |   |                   |   |
|--|------------------------------------|---|-------------------|---|
| Loc ID<br>335901   | Inspector Name:<br>Morris, Matthew | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | <b>Status Summary:</b><br><input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION<br><input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED<br><input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED |
| <b>Operator Information:</b><br>OGCC Operator Number: 10456<br>Name of Operator: CAERUS PICEANCE LLC<br>Address: 1001 17TH STREET #1600<br>City: DENVER State: CO Zip: 80202 |                                    |   |                   | <b>Findings:</b><br>10 Number of Comments<br>0 Number of Corrective Actions<br><input type="checkbox"/> Corrective Action Response Requested  |
|  |                                    |   |                   | <b>ANY CORRECTIVE ACTION(S) FROM<br/>PREVIOUS INSPECTIONS THAT HAVE NOT<br/>BEEN ADDRESSED ARE STILL APPLICABLE</b>   |

| <b>Contact Information:</b> |       |   |         |
|-----------------------------|-------|---|---------|
| Contact Name                | Phone | Email                                     | Comment |
| , CAERUS                    |       | COGCC.inspections@caerus<br>oilandgas.com |         |

| <b>Inspected Facilities:</b> |      |        |             |            |           |                             |             |
|------------------------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| Facility ID                  | Type | Status | Status Date | Well Class | API Num   | Facility Name               | Insp Status |
| 297475                       | WELL | PR     | 10/05/2009  | GW         | 045-16853 | N. PARACHUTE EF15B D19B 595 | PR          |
| 297825                       | WELL | PR     | 10/13/2009  | GW         | 045-16969 | N. PARACHUTE EF06C D19B 595 | PR          |
| 297826                       | WELL | PR     | 11/01/2009  | GW         | 045-16970 | N. PARACHUTE EF10D D19B 595 | PR          |
| 297827                       | WELL | PR     | 10/04/2009  | GW         | 045-16971 | N. PARACHUTE EF14C D19B 595 | PR          |
| 297828                       | WELL | PR     | 11/01/2009  | GW         | 045-16972 | N. PARACHUTE EF07D D19B 595 | PR          |
| 297829                       | WELL | PR     | 11/01/2009  | GW         | 045-16973 | N. PARACHUTE EF06D D19B 595 | PR          |
| 297830                       | WELL | PR     | 11/01/2009  | GW         | 045-16974 | N. PARACHUTE EF10C D19B 595 | PR          |
| 297831                       | WELL | PR     | 11/01/2009  | GW         | 045-16975 | N. PARACHUTE EF10B D19B 595 | PR          |
| 297833                       | WELL | PR     | 11/01/2009  | GW         | 045-16976 | N. PARACHUTE EF10A D19B 595 | PR          |
| 297834                       | WELL | PR     | 10/04/2009  | GW         | 045-16977 | N. PARACHUTE EF14A D19B 595 | PR          |
| 297836                       | WELL | PR     | 10/04/2009  | GW         | 045-16978 | N. PARACHUTE EF15A D19B 595 | PR          |
| 297837                       | WELL | PR     | 07/01/2018  | GW         | 045-16979 | N. PARACHUTE EF08C D19B 595 | PR          |
| 297838                       | WELL | PR     | 12/01/2009  | GW         | 045-16980 | N. PARACHUTE EF08B D19B 595 | PR          |
| 297839                       | WELL | PR     | 12/01/2009  | GW         | 045-16981 | N. PARACHUTE EF03D D19B 595 | PR          |

|        |      |    |            |    |           |                                |    |
|--------|------|----|------------|----|-----------|--------------------------------|----|
| 297840 | WELL | PR | 12/01/2009 | GW | 045-16982 | N. PARACHUTE EF02D<br>D19B 595 | PR |
| 297841 | WELL | PR | 06/06/2008 | GW | 045-16983 | N. PARACHUTE EF04B<br>D19B 595 | PR |
| 297842 | WELL | PR | 11/01/2009 | GW | 045-16984 | N. PARACHUTE EF06A<br>D19B 595 | PR |
| 298923 | WELL | PR | 10/25/2009 | GW | 045-17475 | N. PARACHUTE EF11B<br>D19B 595 | PR |
| 298924 | WELL | PR | 10/04/2009 | GW | 045-17476 | N. PARACHUTE EF11C<br>D19B 595 | PR |
| 298925 | WELL | PR | 09/29/2009 | GW | 045-17477 | N. PARACHUTE EF14B<br>D19B 595 | PR |
| 298926 | WELL | PR | 12/01/2009 | GW | 045-17478 | N. PARACHUTE EF07B<br>D19B 595 | PR |
| 298927 | WELL | PR | 10/03/2009 | GW | 045-17479 | N. PARACHUTE EF11D<br>D19B 595 | PR |
| 298928 | WELL | PR | 12/01/2009 | GW | 045-17480 | N. PARACHUTE EP07C<br>D19B 595 | PR |
| 298936 | WELL | PR | 10/04/2009 | GW | 045-17481 | N. PARACHUTE EF11A<br>D19B 595 | PR |

**General Comment:**

COGCC Inspection Report Summary

On 1/18/2024 at approximately 12:35, Compliance Inspector Matthew Morris conducted an on-site inspection at CAERUS PICEANCE LLC, N. PARACHUTE-65S95W/19LOT 2 at Location ID #335901 in Garfield County, Colorado.

Normal production operations were observed.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**Overall Good: ☐**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | BATTERY              |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

**Emergency Contact Number:**

Comment: 911/(970) 285-2615

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               | WELLHEAD   |       |  |
| Comment:           | Concrete barriers                                |       |  |
| Corrective Action: |  | Date: |  |
| Type               | OTHER  |       |  |
| Comment:           | Gas meters/lifts protected by concrete barriers. |       |  |
| Corrective Action: |  | Date: |  |

**Equipment:**

|                            |              |       |                 |
|----------------------------|--------------|-------|-----------------|
| Type: Horizontal Separator | # 2          |       | corrective date |
| Comment:                   | Mobile units |       |                 |
| Corrective Action:         |              | Date: |                 |
| Type: Gas Meter Run        | # 4          |       |                 |
| Comment:                   | Gas lift     |       |                 |
| Corrective Action:         |              | Date: |                 |
| Type: Gas Meter Run        | # 20         |       |                 |
| Comment:                   | Gas lift     |       |                 |
| Corrective Action:         |              | Date: |                 |
| Type: Gas Meter Run        | # 20         |       |                 |

|                           |                |  |       |
|---------------------------|----------------|--|-------|
| Comment:                  |                |  |       |
| Corrective Action:        |                |  | Date: |
| Type: Plunger Lift        | # 4            |  |       |
| Comment:                  |                |  |       |
| Corrective Action:        |                |  | Date: |
| Type: Bradenhead          | # 20           |  |       |
| Comment:                  |                |  |       |
| Corrective Action:        |                |  | Date: |
| Type: Gas Meter Run       | # 4            |  |       |
| Comment:                  |                |  |       |
| Corrective Action:        |                |  | Date: |
| Type: Ancillary equipment | # 3            |  |       |
| Comment:                  | Chemical tanks |  |       |
| Corrective Action:        |                |  | Date: |
| Type: Bradenhead          | # 4            |  |       |
| Comment:                  |                |  |       |
| Corrective Action:        |                |  | Date: |
| Type: Plunger Lift        | # 20           |  |       |
| Comment:                  |                |  |       |
| Corrective Action:        |                |  | Date: |

**Tanks and Berms:**

|                    |   |           |           |         |        |       |
|--------------------|---|-----------|-----------|---------|--------|-------|
| Contents           | # | Capacity  | Type      | Tank ID | SE GPS |       |
| PRODUCED WATER     | 1 | <100 BBLS | STEEL AST |         | ,      |       |
| Comment:           |   |           |           |         |        |       |
| Corrective Action: |   |           |           |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 80 bbls  |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          |                     | Date:               |             |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    |       |  |
|                    |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities  |        |       |      |             |           |         |    |               |    |
|-----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 297475 | Type: | WELL | API Number: | 045-16853 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |        |       |      |             |           |         |    |               |    |
| Comment:              |        |       |      |             |           |         |    |               |    |
| Corrective Action:    |        |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 297825 | Type: | WELL | API Number: | 045-16969 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |        |       |      |             |           |         |    |               |    |
| Comment:              |        |       |      |             |           |         |    |               |    |
| Corrective Action:    |        |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 297826 | Type: | WELL | API Number: | 045-16970 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |        |       |      |             |           |         |    |               |    |
| Comment:              |        |       |      |             |           |         |    |               |    |
| Corrective Action:    |        |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 297827 | Type: | WELL | API Number: | 045-16971 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |        |       |      |             |           |         |    |               |    |
| Comment:              |        |       |      |             |           |         |    |               |    |
| Corrective Action:    |        |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 297828 | Type: | WELL | API Number: | 045-16972 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |        |       |      |             |           |         |    |               |    |
| Comment:              |        |       |      |             |           |         |    |               |    |
| Corrective Action:    |        |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 297829 | Type: | WELL | API Number: | 045-16973 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |        |       |      |             |           |         |    |               |    |
| Comment:              |        |       |      |             |           |         |    |               |    |
| Corrective Action:    |        |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 297830 | Type: | WELL | API Number: | 045-16974 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |        |       |      |             |           |         |    |               |    |
| Comment:              |        |       |      |             |           |         |    |               |    |
| Corrective Action:    |        |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 297831 | Type: | WELL | API Number: | 045-16975 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |        |       |      |             |           |         |    |               |    |
| Comment:              |        |       |      |             |           |         |    |               |    |
| Corrective Action:    |        |       |      |             |           | Date:   |    |               |    |

|                              |        |       |      |             |           |         |    |               |    |
|------------------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:                 | 297833 | Type: | WELL | API Number: | 045-16976 | Status: | PR | Insp. Status: | PR |
| <b><u>Producing Well</u></b> |        |       |      |             |           |         |    |               |    |
| Comment:                     |        |       |      |             |           |         |    |               |    |
| Corrective Action:           |        |       |      |             |           | Date:   |    |               |    |
|                              |        |       |      |             |           |         |    |               |    |
| Facility ID:                 | 297834 | Type: | WELL | API Number: | 045-16977 | Status: | PR | Insp. Status: | PR |
| <b><u>Producing Well</u></b> |        |       |      |             |           |         |    |               |    |
| Comment:                     |        |       |      |             |           |         |    |               |    |
| Corrective Action:           |        |       |      |             |           | Date:   |    |               |    |
|                              |        |       |      |             |           |         |    |               |    |
| Facility ID:                 | 297836 | Type: | WELL | API Number: | 045-16978 | Status: | PR | Insp. Status: | PR |
| <b><u>Producing Well</u></b> |        |       |      |             |           |         |    |               |    |
| Comment:                     |        |       |      |             |           |         |    |               |    |
| Corrective Action:           |        |       |      |             |           | Date:   |    |               |    |
|                              |        |       |      |             |           |         |    |               |    |
| Facility ID:                 | 297837 | Type: | WELL | API Number: | 045-16979 | Status: | PR | Insp. Status: | PR |
| <b><u>Producing Well</u></b> |        |       |      |             |           |         |    |               |    |
| Comment:                     |        |       |      |             |           |         |    |               |    |
| Corrective Action:           |        |       |      |             |           | Date:   |    |               |    |
|                              |        |       |      |             |           |         |    |               |    |
| Facility ID:                 | 297838 | Type: | WELL | API Number: | 045-16980 | Status: | PR | Insp. Status: | PR |
| <b><u>Producing Well</u></b> |        |       |      |             |           |         |    |               |    |
| Comment:                     |        |       |      |             |           |         |    |               |    |
| Corrective Action:           |        |       |      |             |           | Date:   |    |               |    |
|                              |        |       |      |             |           |         |    |               |    |
| Facility ID:                 | 297839 | Type: | WELL | API Number: | 045-16981 | Status: | PR | Insp. Status: | PR |
| <b><u>Producing Well</u></b> |        |       |      |             |           |         |    |               |    |
| Comment:                     |        |       |      |             |           |         |    |               |    |
| Corrective Action:           |        |       |      |             |           | Date:   |    |               |    |
|                              |        |       |      |             |           |         |    |               |    |
| Facility ID:                 | 297840 | Type: | WELL | API Number: | 045-16982 | Status: | PR | Insp. Status: | PR |
| <b><u>Producing Well</u></b> |        |       |      |             |           |         |    |               |    |
| Comment:                     |        |       |      |             |           |         |    |               |    |
| Corrective Action:           |        |       |      |             |           | Date:   |    |               |    |
|                              |        |       |      |             |           |         |    |               |    |
| Facility ID:                 | 297841 | Type: | WELL | API Number: | 045-16983 | Status: | PR | Insp. Status: | PR |
| <b><u>Producing Well</u></b> |        |       |      |             |           |         |    |               |    |
| Comment:                     |        |       |      |             |           |         |    |               |    |
| Corrective Action:           |        |       |      |             |           | Date:   |    |               |    |

|                              |        |       |      |             |           |         |    |               |       |
|------------------------------|--------|-------|------|-------------|-----------|---------|----|---------------|-------|
| Facility ID:                 | 297842 | Type: | WELL | API Number: | 045-16984 | Status: | PR | Insp. Status: | PR    |
| <b><u>Producing Well</u></b> |        |       |      |             |           |         |    |               |       |
| Comment:                     |        |       |      |             |           |         |    |               |       |
| Corrective Action:           |        |       |      |             |           |         |    |               | Date: |
|                              |        |       |      |             |           |         |    |               |       |
| Facility ID:                 | 298923 | Type: | WELL | API Number: | 045-17475 | Status: | PR | Insp. Status: | PR    |
| <b><u>Producing Well</u></b> |        |       |      |             |           |         |    |               |       |
| Comment:                     |        |       |      |             |           |         |    |               |       |
| Corrective Action:           |        |       |      |             |           |         |    |               | Date: |
|                              |        |       |      |             |           |         |    |               |       |
| Facility ID:                 | 298924 | Type: | WELL | API Number: | 045-17476 | Status: | PR | Insp. Status: | PR    |
| <b><u>Producing Well</u></b> |        |       |      |             |           |         |    |               |       |
| Comment:                     |        |       |      |             |           |         |    |               |       |
| Corrective Action:           |        |       |      |             |           |         |    |               | Date: |
|                              |        |       |      |             |           |         |    |               |       |
| Facility ID:                 | 298925 | Type: | WELL | API Number: | 045-17477 | Status: | PR | Insp. Status: | PR    |
| <b><u>Producing Well</u></b> |        |       |      |             |           |         |    |               |       |
| Comment:                     |        |       |      |             |           |         |    |               |       |
| Corrective Action:           |        |       |      |             |           |         |    |               | Date: |
|                              |        |       |      |             |           |         |    |               |       |
| Facility ID:                 | 298926 | Type: | WELL | API Number: | 045-17478 | Status: | PR | Insp. Status: | PR    |
| <b><u>Producing Well</u></b> |        |       |      |             |           |         |    |               |       |
| Comment:                     |        |       |      |             |           |         |    |               |       |
| Corrective Action:           |        |       |      |             |           |         |    |               | Date: |
|                              |        |       |      |             |           |         |    |               |       |
| Facility ID:                 | 298927 | Type: | WELL | API Number: | 045-17479 | Status: | PR | Insp. Status: | PR    |
| <b><u>Producing Well</u></b> |        |       |      |             |           |         |    |               |       |
| Comment:                     |        |       |      |             |           |         |    |               |       |
| Corrective Action:           |        |       |      |             |           |         |    |               | Date: |
|                              |        |       |      |             |           |         |    |               |       |
| Facility ID:                 | 298928 | Type: | WELL | API Number: | 045-17480 | Status: | PR | Insp. Status: | PR    |
| <b><u>Producing Well</u></b> |        |       |      |             |           |         |    |               |       |
| Comment:                     |        |       |      |             |           |         |    |               |       |
| Corrective Action:           |        |       |      |             |           |         |    |               | Date: |
|                              |        |       |      |             |           |         |    |               |       |
| Facility ID:                 | 298936 | Type: | WELL | API Number: | 045-17481 | Status: | PR | Insp. Status: | PR    |
| <b><u>Producing Well</u></b> |        |       |      |             |           |         |    |               |       |
| Comment:                     |        |       |      |             |           |         |    |               |       |
| Corrective Action:           |        |       |      |             |           |         |    |               | Date: |
|                              |        |       |      |             |           |         |    |               |       |

|  |
|--|
|  |
|--|

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment                                 |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---|
| Compaction       |                 |                         |                       |  |                          |   |
|                  |                 | Compaction              |                       |  |                          |   |
|                  |                 | Gravel                  |                       |  |                          |   |
|                  |                 |                         |                       | Material Handling And Spill Prevention |                          | Chemical tanks in secondary containment |
|                  |                 | Ditches                 |                       |  |                          |   |
| Berms            |                 |                         |                       |  |                          |   |
|                  |                 | Culverts                |                       |  |                          |   |

Comment: Location surface is frozen. Unable to inspect all Stormwater BMPs due to snow cover.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 708301561    | Photo Log   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6401009">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6401009</a> |