

WELL NAME: NAPOLEAN 12-10, API #: 071-09043, INSP. # 695109033



PHOTO 1: WELL SIGN



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



PHOTO 2: LOCATION





PHOTO 3: WELLHEAD AND EQUIPMENT





PHOTO 4: LARGE AREA OF IMPACTED SOIL AROUND COMPRESSOR INSIDE AND OUTSIDE OF SOUND MITIGATION SHED. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. CA DATE 2-22-2024.





PHOTO 5: OILY WASTE IN ENGINE SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. PER RULE 1002,.(2).D. Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 1-23-2024.





PHOTO 6: LEAKS ON COMPRESSOR MOTOR AND EQUIPMENT. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. PER RULE 1002,.(2).D. Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 2-22-2024.

