

Inspection Photos

Location Name: HERRERA-N33N12W/26NWE (OWP)

Location ID: 325511



Cement to surface.



Well cut and cap plate.