

Inspection Photos
Location Name: Lee 1-10
Location ID: 319155



Photo 1: Location from entrance

Photo 2: Tank Battery

Inspection Photos
Location Name: Lee 1-10
Location ID: 319155



Photo 3: Equipment

Photo 4: Location of Wellhead

Inspection Photos
Location Name: Lee 1-10
Location ID: 319155




Photo 5: Wellhead Sign

Photo 6: SI Wellhead