

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: DOWDY 62N65W / 10 NESE/8-6-10

Loc ID: 430092

Inspection: 714200515



Exhibit A

CA: It appears to be unused/disconnected automation near ECDs. See attached photos. Comply with Rule 606.

CA Resolution: Operator has reported that the unused equipment has been removed from the location to comply with Rule 606.