

Final Reclamation Inspection

Date: 1/19/24

Operator: Bonanza Creek Energy Operating
Company LLC - 8960

Location ID: 423761

Inspection Document #: 713900295

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Antelope I-20
Location ID: 423761



Photo 1. The photo was taken from the well location facing East. The photo illustrates the abandoned well on the closed location.



Photo 2. The photo was taken from the well location facing Northwest. Refer to the comment for photo 1.