

Inspection Photos
Location Name: GEMINI-65N64W/29SWNW
Location #: 336618



Photo #1

Fairbanks B 29-31 Wellsite
Temporarily Abandoned | TA
Gemini B29-5 Wellsite
Plugged & Abandoned | PA
2 - well pad



Photo #2

Fairbanks B 29-31 (123-25680) Wellsite
Temporarily Abandoned | TA



Inspection Photos

Location Name: GEMINI-65N64W/29SWNW

Location #: 336618



Photo #3

**Heldt B 29-20, 29-32, Fairbanks B 29-31,
Gemini B 29-19** Battery site

Abandoned: ALL Equipment Removed

Formerly served:

Heldt B 29-21, Gemini B29-5, B29-6,

Ocoma UPRR Lease B29-12 ;

Plugged & Abandoned | PA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources