

# Inspection Photos

Location Name: GEMINI-65N64W/29SWNW

Location #: 336618



Colorado Energy & Carbon Management Commission  
Weld County  
+40.371846, -104.580821  
62° NE  
2024-01-18 13:51

**Photo #1**

**Fairbanks B 29-31** Wellsite

**Temporarily Abandoned | TA**

**Gemini B29-5** Wellsite

**Plugged & Abandoned | PA**

*2 - well pad*



Colorado Energy & Carbon Management Commission  
Weld County  
+40.371878, -104.580935  
62° NE  
2024-01-18 15:50

**Photo #2**

**Gemini B29-5 (123-13697)** Wellsite

**Plugged & Abandoned | PA**

*Cut / Capped*

*~ 10 yds.*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: GEMINI-65N64W/29SWNW

Location #: 336618



### Photo #3

**Heldt B 29-20, 29-32, Fairbanks B 29-31,  
Gemini B 29-19** Battery site

**Abandoned: ALL Equipment Removed**

*Formerly served:*

*Heldt B 29-21, Gemini B29-5, B29-6,*

*Ocoma UPRR Lease B29-12 ;*

*Plugged & Abandoned | PA*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources