

Final Reclamation Inspection

January 22nd, 2024

Operator: Simcoe LLC - 10749

Location ID: 306845

Inspection Document #: 714000331

La Plata County, CO

Township: NESW 10 34N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**


Department of Natural Resources

Inspection Photos
Location Name: Webb Reeder A-2
Location ID: 306845



1/22/24
+37.219483,-107.844125
246° SW

Photo 1. View of the disturbance from the entrance facing center.



API #: 067-08877



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Webb Reeder A-2
Location ID: 306845



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of western interim reclamation area facing south.
Interim vegetation was not fully assessed due to snowy conditions.

API #: 067-08877

Inspection Photos
Location Name: Webb Reeder A-2
Location ID: 306845



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of closed gate leaving location.

API #: 067-08877