

Final Reclamation Inspection

January 22nd, 2024

Operator: Simcoe LLC - 10749

Location ID: 325411

Inspection Document #: 714000337

La Plata County, CO

Township: NWSE 11 34N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Xavier 1
Location ID: 325411



Photo 1. View of the disturbance from the entrance facing center.

Inspection Photos
Location Name: Xavier 1
Location ID: 325411

1/22/24
+37.228076,-107.711735
217° SW



Photo 2. View of the western interim reclamation area. Interim vegetation was not fully assessed due to snowy conditions.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06337