

# Inspection Photos

1/22/2024

**Operator:** CAERUS PICEANCE LLC #10456

**Location ID:** 334670

**Inspection Doc:** 696205567

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334670



**Photo 1:** Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location from southwest, northwest, north to northeast.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334670



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334670



**Photo 3:** Photos taken from the interim areas. Photos examples showing Noxious weed (Musk thistle) remnants established during the prior growing season. Additional weed management efforts required during the 2024 growing season.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location ID: 334670




**Photo 4:** Photo example showing unmarked anchors on the Location.

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334670



**Photo 5:** Photo left shows piping at separator equipment lacks BMPs to prevent wildlife entry; pipe is open ended. Photo right example showing piping at tank battery Location with adequate wildlife protection BMPs at piping.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334670



**Photo 6:** Capacity information at tank no longer legible.