

Inspection Photos

1/22/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 334589

Inspection Doc: 696205571

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334589



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location from south, southwest, northwest and north.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334589



January 22, 2024



January 22, 2024

Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334589



Photo 3: Example of anchor markers that do not comport with 1003.a / 606.j




January 22, 2024

Photo 4: Photos show electrical/solar equipment; equipment appears to be disconnected and unused.

Inspection P
CAERUS P
Location ID:



January 22, 2024



January 22, 2024



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources