

# Inspection Photos

1/22/2024

**Operator:** CAERUS PICEANCE LLC #10456

**Location ID:** 334642

**Inspection Doc:** 696205573

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334642



**Photo 1:** Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location from southwest to northwest..



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334642



**Photo 2:** Mousehole used during drilling operations left on Location and covered with a rock; reclamation specialist replaced rock upon completion of inspection for safety purposes. Mousehole requires removal/backfilling



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



**Photo 3:** Photos examples showing various trash/debris observed on the Location.



Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334642



**Photo 3:** Unused pipe stored within the battery facility's containment BMP.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources