

Inspection Photos
Location Name: McClellan 33--20
Location ID: 328874



Production facility



Debris at wellhead

Inspection Photos
Location Name: McClellan 33--20
Location ID: 328874



Energy & Carbon Management Commission
40.29572, -104.7985, 1432.8m, 115°
01/24/2024 11:31:46

Wellhead sign and debris