

Beeman Oil & Gas Inc  
Elk Springs Unit 3  
Loc ID: 311768



**Access road to location**



**Unlabeled container. Containment open to wildlife.**

Beeman Oil & Gas Inc  
Elk Springs Unit 3  
Loc ID: 311768



Debris



Debris



Beeman Oil & Gas Inc  
Elk Springs Unit 3  
Loc ID: 311768



Leaking equipment. Oily waste



Oily waste



Beeman Oil & Gas Inc  
Elk Springs Unit 3  
Loc ID: 311768



Debris



Oily waste and debris

**Beeman Oil & Gas Inc  
Elk Springs Unit 3  
Loc ID: 311768**



**Unlabeled drum**



**Debris**



Beeman Oil & Gas Inc  
Elk Springs Unit 3  
Loc ID: 311768



Containment open to wildlife



Debris



Beeman Oil & Gas Inc  
Elk Springs Unit 3  
Loc ID: 311768



Debris



Debris



**Beeman Oil & Gas Inc  
Elk Springs Unit 3  
Loc ID: 311768**



**Debris. Evidence of fluid drained to production pit**



**Production pit**



Beeman Oil & Gas Inc  
Elk Springs Unit 3  
Loc ID: 311768



Open ended load line



Debris



Beeman Oil & Gas Inc  
Elk Springs Unit 3  
Loc ID: 311768



Production tank missing required information



Debris



**Beeman Oil & Gas Inc  
Elk Springs Unit 3  
Loc ID: 311768**



**Location from Northwest corner**



**Location from Northeast corner**



**Beeman Oil & Gas Inc  
Elk Springs Unit 3  
Loc ID: 311768**



**Location from Southeast corner**



**Location from Southwest corner**