

Inspection Photos
Location Name: ABBOTT FARMS 1
Location ID: 320050



Photo #1 Crude tank.



Photo #2 P/w Tank.

Inspection Photos
Location Name: ABBOTT FARMS 1
Location ID: 320050



Photo #3 Meter house.



Photo #4 Separator (weeds around separator).

Inspection Photos
Location Name: ABBOTT FARMS 1
Location ID: 320050




Photo #5 Well Head.