


Beeman Oil & Gas Inc
Diamond T Sheep 7-92 1-26
Loc ID: 438248




Debris



Debris

**Beeman Oil & Gas Inc
Diamond T Sheep 7-92 1-26
Loc ID: 438248**



Debris



Faded and illegible label

Beeman Oil & Gas Inc
Diamond T Sheep 7-92 1-26
Loc ID: 438248



Open to wildlife



Faded and illegible label

Beeman Oil & Gas Inc
Diamond T Sheep 7-92 1-26
Loc ID: 438248




Debris



Debris

Beeman Oil & Gas Inc
Diamond T Sheep 7-92 1-26
Loc ID: 438248



No visible display of gas meter calibration



Unused equipment storage

Beeman Oil & Gas Inc
Diamond T Sheep 7-92 1-26
Loc ID: 438248



Unused equipment?



Unused equipment?

**Beeman Oil & Gas Inc
Diamond T Sheep 7-92 1-26
Loc ID: 438248**




Containment open to wildlife



Unused equipment

Beeman Oil & Gas Inc
Diamond T Sheep 7-92 1-26
Loc ID: 438248



Leaking equipment. Oily waste and stained soil.



Debris

Beeman Oil & Gas Inc
Diamond T Sheep 7-92 1-26
Loc ID: 438248




Equipment storage



Equipment and supply storage

Beeman Oil & Gas Inc
Diamond T Sheep 7-92 1-26
Loc ID: 438248



Debris



Chemical tanks lacking required labels

Beeman Oil & Gas Inc
Diamond T Sheep 7-92 1-26
Loc ID: 438248



Tank open to wildlife



Containment open to wildlife

**Beeman Oil & Gas Inc
Diamond T Sheep 7-92 1-26
Loc ID: 438248**



Location from Southeast corner



Location from Southwest corner

**Beeman Oil & Gas Inc
Diamond T Sheep 7-92 1-26
Loc ID: 438248**



Location from Northwest corner



Location from Southwest corner