

**Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC**

**Location Name: North Platte 23-24**

**Loc ID: 310067**

**Inspection: 713900197**



Exhibit A



**Exhibit B**

**CA:** This location does not comply with Rule 1004. Reclamation rules require reclamation activities to be conducted within twelve months of plugging on non-cropland. Well was plugged 06/08/2021. The well location has some evidence of reclamation activities with evidence of few perennial grasses germinating on location. Operator has failed to reclaim the access road and the well location area is dominated by Russian thistle, kochia and bare soil patches. Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

**CA Resolution:** Operator has reported that reclamation activity, including clearing of weeds, reseeding location, and stabilizing with crimped straw to promote vegetation growth, has been completed as of 1/23/2024. Operator has also noted that a small fence has been installed to prevent vehicles from driving on location and disturbing recent work completed. Location is currently in compliance with Rule 1004.