

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: State Antelope 41-15HZ

Loc ID: 422729

Inspection: 696305488



Exhibit A

CA: Unused Pollution Pot and Trash at Pumping Unit; see photos. Comply with Rule 606

CA Resolution: Operator has reported that unused pollution pot and additional trash identified at the pumping unit have been cleared to comply with Rule 606.