

Inspection Photos
Location Name: Sutton 41-21
Location ID: 332235



Photo 1 well head and equipment



Photo 2 well head and equipment

Inspection Photos
Location Name: Sutton 41-21
Location ID: 332235



Photo 3 branden head leak



Photo 4 braden head leak

Inspection Photos
Location Name: Sutton 41-21
Location ID: 332235



Photo 5 production equipment



Photo 6 production equipment

Inspection Photos
Location Name: Sutton 41-21
Location ID: 332235



Photo 7 tank battery



Photo 8 tank battery