

**Operator: EXTRACTION OIL & GAS INC**  
**Location Name: KILKER-61S69W 15SENE**  
**Loc ID: 321372**  
**Inspection: 699505277**




Exhibit A

**CA:** Gas meter run has not been calibrated since 2019 and is in need of calibration. Calibrate gas metering equipment annually to comply with rule 430.d.(1).

**CA Resolution:** As of 1/24/2024, the identified gas meter has been calibrated, and the card has been appropriately updated to comply with Rule 430.d.(1).