

**Operator: CRESTONE PEAK RESOURCES OPERATING LLC**

**Location Name: Tebo 3/1H**

**Loc ID: 430346**

**Inspection: 709400707**

### Watkins CO

☉ 21°N (T) ● 39°39'0"N, 104°31'50"W ±13ft ▲ 5879ft



31 H north east

Tebo  
24 Jan 2024

Exhibit A

### Watkins CO

☉ 347°N (T) ● 39°39'1"N, 104°31'48"W ±9ft ▲ 5874ft



31 H north area

Tebo  
24 Jan 2024

Exhibit B




Exhibit C

**CA:** Failure to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands. Comply with Rule 606.c. The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date the location was observed out of compliance.

**CA Resolution:** Operator has reported that the identified weeds and weed debris on location has been appropriately addressed and cleared to comply with Rule 606.