

Inspection Photos

Loc: 322266

Operator: **JAVERNICK OIL**

Inspection Date: 1/23/2024

County: **FREMONT**



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east at the abandoned wellsite. The site has not been reclaimed and there are undesirable weeds and bare soil in this area of the wellsite.



Inspection Photos



Photo 2. Facing southeast at the wellsite. There is bare soils and scattered debris remnants that remain.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:322266 | Date: 1/23/2024

Inspection Photos



Photo 3. Facing west at the wellsite. There is bare soils and scattered debris remnants that remain.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:322266 | Date: 1/23/2024