

Inspection Photos

Loc: 322263

Operator: **JAVERNICK OIL**

Inspection Date: 1/23/2024

County: FREMONT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 3. Facing southwest at the abandoned wellsite. There is a pipe at red arrow and weed block.



Inspection Photos



Photo 2. There is stained soils at red arrow and a metal rod.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:322263 | Date: 1/23/2024