



Photos  
taken by  
Kris  
Neidel

Location:  
324639

REM:  
17342

01.25.2024 14:17



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Photo #1 corner of tank battery in center of photo. Note: sign at old fence.



Photos  
taken by  
Kris  
Neidel

Location:  
324639

REM:  
17342

01.25.2024 14:17






Photos  
taken by  
Kris  
Neidel

Location:  
324639

REM:  
17342





Photos  
taken by  
Kris  
Neidel


Location:  
324639

REM:  
17342



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Photo #4 electric fencing around stock piled soil. Snow cover was deep, it appeared that some BMP's were staked into the ground around the pile.



Photos  
taken by  
Kris  
Neidel

Location:  
324639

REM:  
17342



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Photo #5 Stock piled soil. Note: fencing and electric fence is down and in snow.



Photos  
taken by  
Kris  
Neidel

Location:  
324639

REM:  
17342

01.25.2024 14:18



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Photo #6 Stock piled soil. Note: fencing and electric fence is down and in snow.



Photos  
taken by  
Kris  
Neidel

Location:  
324639

REM:  
17342

01.25.2024 14:19



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo #7 looking to the northeast across surface ditch. Note;  
wood stakes in ground.**



Photos  
taken by  
Kris  
Neidel

Location:  
324639

REM:  
17342

01.25.2024 14:19



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Photo #8 looking southwest at surface water ditch and stock piled soil.



Photos  
taken by  
Kris  
Neidel

Location:  
324639

REM:  
17342



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Photo #9 west side of stockpile.