

Inspection Photos on 1/25/24

Location Name: Dawson A2

API: 05-061-06043



**East side of unit looking west at wellhead.
Showing area of spill and removed soil**



**Southeast of wellhead showing area of
spill and removed soil**

Soil was removed on the same day the spill occurred and was reported



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos on 1/25/24

Location Name: Dawson A2

API: 05-061-06043



West side of unit looking at wellhead. Showing area of spill and removed soil



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources