

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Speakman/A Pad

Location ID: 422301

Date: 1/25/2024



Location Entrance – Photo #08852



Wellheads – Photo #08857

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Speakman/A Pad

Location ID: 422301

Date: 1/25/2024



Wellheads – Photo #08859



Separators – Photo #08856

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Speakman/A Pad

Location ID: 422301

Date: 1/25/2024



Tank Battery – Photo #08853



Tank Battery – Photo #08858

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Speakman/A Pad

Location ID: 422301

Date: 1/25/2024



ECD – Photo #08855



Lack of Stabilization – Photo #08860

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Speakman/A Pad

Location ID: 422301

Date: 1/25/2024



Lack of Stabilization – Photo #08861



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #08863**