

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403653342

Date Received:
01/12/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Romana Cowden</u>	<u>720-951-5895</u>	<u>COGCC.inspections@caerusoilandgas.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202866
Inspection Date: 06/25/2021 FIR Submit Date: 06/29/2021 FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC Company Number: 10456
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335573

Location Name: N. Parachute Number: EF G29 595 County: _____
Qtrqtr: SWNE Sec: 29 Twp: 5S Range: 95W Meridian: 6
Latitude: 39.585810 Longitude: -108.074280

FACILITY - API Number: 05-045-00 Facility ID: 335573

Facility Name: N. Parachute Number: EF G29 595
Qtrqtr: SWNE Sec: 29 Twp: 5S Range: 95W Meridian: 6
Latitude: 39.585810 Longitude: -108.074280

CORRECTIVE ACTIONS:

1 CA# 152322

Corrective Action: Submit documentation and demonstration of compliance with the 1/5/2017 COGCC NTO for Interim Reclamation Procedures for Delayed Operations, this would include estimates for removal, transport and disposal in addition to the cost to perform interim reclamation.

Operator shall submit the required documentation attached to a Form 4 to NW EPS Arauza, and NW Reclamation Specialist Trujillo.

Date: 07/01/2017

Response: CA COMPLETED Date of Completion: 01/11/2024

Supplemental Form 27 Doc # 403369784 was approved on 05/24/2023 allowing for the excavation and onsite staging of cuttings material from the interim reclamation area. The excavation, stabilization, and compliance

Operator Comment: sampling was completed in 2023 for approximately 7,000 cubic yards of material. Compliant samples were provided to the CECMC on Supplemental Form 27 Doc # 403594398 and backfill was approved under this document and Form 4 Beneficial Reuse Plan Doc # 403595967. Confirmation sampling and closure of the project will be completed following excavation backfill. Interim reclamation and backfill is complete.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 1/12/2024 12:08:04 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403653342	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files