

**Inspection Photos**  
**Location Name: Wells Ranch USX AE 21-12**  
**Location ID: 310627**



**Photo 1 – Weeds on Lease Road – Looking North towards Pumping Unit**

**Photo 2 – Pumping Unit – Weeds**

**Inspection Photos**  
**Location Name: Wells Ranch USX AE 21-12**  
**Location ID: 310627**



**Photo 3 – Pumping Unit**

**Photo 4 – Wellhead Sign**

**Inspection Photos**  
**Location Name: Wells Ranch USX AE 21-12**  
**Location ID: 310627**



Energy and Carbon Management Commission  
40.4707, -104.33471, 4792.8ft  
01/24/2024 14:09:19



Energy and Carbon Management Commission  
40.47068, -104.33473, 4793.6ft  
01/24/2024 14:09:44

**Photo 5 – Wellhead**

**Photo 6 – Lease Road looking Southeast to Tank Battery**