

Inspection Photos
Location Name: Wells Ranch USX AE 21-12 Tank Battery
Location ID: 467490



Photo 1 – Separator, ECD and Gas Meter – Weeds



Photo 2 – Tank Battery – Weeds



Inspection Photos
Location Name: Wells Ranch USX AE 21-12 Tank Battery
Location ID: 467490



Photo 3 – Pumping Unit



Photo 4 – Tumbleweed Debris

