

Inspection Photos
Location Name: Wells Ranch USX AE 21-99HZ Tank Battery
Location ID: 415229



Photo 1 – ECDs – Tumbleweeds



Photo 2 – Separators – Tumbleweeds

Inspection Photos
Location Name: Wells Ranch USX AE 21-99HZ Tank Battery
Location ID: 415229



Photo 3 – Tank Battery – Tumbleweeds



Photo 4 – Tank Battery Sign

Inspection Photos

Location Name: Wells Ranch USX AE 21-99HZ Tank Battery

Location ID: 415229



Photo 5 – Tank Battery – Tumbleweeds



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources