

Inspection Photos
Location Name: Grande 4-65 20-19 3AH
Location ID: 450063

an 23, 2024 at 12:33:39 PM
39.685476,-104.676861
rapahoe County
ECMC



Pic 1 wellheads

an 23, 2024 at 12:34:18 PM
39.686263,-104.676725
rapahoe County
ECMC



Pic 2 wellhead

Inspection Photos
Location Name: Grande 4-65 20-19 3AH
Location ID: 450063



Pic 3 Solar / automation



Pic 4 Electric, Flare, ECD.

Inspection Photos
Location Name: Grande 4-65 20-19 3AH
Location ID: 450063

Jan 23, 2024 at 12:35:02 PM
39.686396,-104.676218
Wapahoe County
ECMC



Jan 23, 2024 at 12:35:11 PM
39.686316,-104.676142
Wapahoe County
ECMC



Pic 5 Separators, GMR, Electric, VRU

Pic 6 Tanks, VRT

Inspection Photos
Location Name: Grande 4-65 20-19 3AH
Location ID: 450063



Pic 7 Tanks, LACT



Pic 8 Electric, VRT, VRU, ECD.

Inspection Photos
Location Name: Grande 4-65 20-19 3AH
Location ID: 450063

an 23, 2024 at 12:36:34 PM
39.685380,-104.676120
rapahoe County
ECMC



Pic 9 Separators

an 23, 2024 at 12:36:59 PM
39.685059,-104.676107
rapahoe County
ECMC



Pic 10 Compressor