

Inspection Photos
Location Name: Harriet W Lucke 2
Location ID: 318269



Pic 1 Wellhead, pumpjack.



Pic 2 leak on piping for bradenhead, gauge shows 17 PSI on bradenhead.