

Final Reclamation Inspection

January 25th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325508

Inspection Document #: 714000346

La Plata County, CO

Township: NENE 13 34N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Sitton 01-13 1
Location ID: 325508

1/25/24
+37.218482,-107.583112
192° S



Photo 1. View of the disturbance from the entrance facing center.

Inspection Photos
Location Name: Sitton 01-13 1
Location ID: 325508

1/25/24
+37.218382,-107.582751
298° NW



Photo 2. View of surface owner equipment stored in the northern portion of the disturbance.

Inspection Photos
Location Name: Sitton 01-13 1
Location ID: 325508



Photo 3. Stained soils around muffler have been removed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Sitton 01-13 1
Location ID: 325508

1/25/24
+37.218081,-107.582728
239° SW



Photo 4. View of southern interim reclamation area. Area is dominated by weedy kochia debris.



Inspection Photos
Location Name: Sitton 01-13 1
Location ID: 325508

1/25/24
+37.218522,-107.583378
64° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area comprised of tumble mustard and smooth brome.

API #: 067-06516