

# Final Reclamation Inspection

January 25th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306841

Inspection Document #: 714000347

La Plata County, CO

Township: NWNE 14 34N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Snooks A2  
Location ID: 306841



**Photo 1.** View of the disturbance from the entrance facing center.



API #: 067-08870



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Snooks A2  
Location ID: 306841



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of surface owner equipment stored in the eastern portion of the disturbance.

API #: 067-08870



Inspection Photos  
Location Name: Snooks A2  
Location ID: 306841



**Photo 3.** Patches of spotted knapweed observed around the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-08870



Inspection Photos  
Location Name: Snooks A2  
Location ID: 306841



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** View of additional trailers/equipment stored on the eastern edge of the disturbance.

API #: 067-08870



Inspection Photos  
Location Name: Snooks A2  
Location ID: 306841



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Reference area comprised of smooth brome and cottonwoods.

API #: 067-08870