

# Final Reclamation Inspection

January 25th, 2024

Operator: Simcoe LLC - 10749

Location ID: 334264

Inspection Document #: 714000348

La Plata County, CO

Township: NWNW 9 34N 7W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: French 01-9U 1, 3  
Location ID: 334264

1/25/24  
+37.210695,-107.618638  
234° SW



Photo 1. View of the disturbance from the entrance facing center.



Inspection Photos  
Location Name: French 01-9U 1, 3  
Location ID: 334264



1/25/24  
+37.210551,-107.618510  
189° S



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of eastern interim reclamation area facing south. Interim vegetation was not fully assessed due to snowy conditions.

API #: 067-06563, 09655

Inspection Photos  
Location Name: French 01-9U 1, 3  
Location ID: 334264



**Photo 3.** Trash observed on location.



Inspection Photos  
Location Name: French 01-9U 1, 3  
Location ID: 334264



**Photo 4.** Unused equipment/traffic marker signs observed in previous inspection have been removed from the location.

Inspection Photos  
Location Name: French 01-9U 1, 3  
Location ID: 334264

1/25/24  
+37.210768,-107.618472  
22° N



Photo 5. Berm CA from previous inspection has been addressed.