

Final Reclamation Inspection

January 25th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325632

Inspection Document #: 714000350

La Plata County, CO

Township: NENW 11 34N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Le Platt 1
Location ID: 325632



Photo 1. View of the disturbance from the entrance facing center.



Inspection Photos
Location Name: Le Platt 1
Location ID: 325632



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of unused equipment and trash (likely surface owners) stored in the eastern and western interim reclamation areas on the edge of the disturbance.

API #: 067-06743

Inspection Photos
Location Name: Le Platt 1
Location ID: 325632



1/25/24
+37.233391,-107.606987
19° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of additional unused equipment (likely surface owners) stored on the location.

API #: 067-06743