

Final Reclamation Inspection

January 25th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326675

Inspection Document #: 714000351

La Plata County, CO

Township: NWSW 2 34N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Paisley 2
Location ID: 326675



1/25/24
+37.240691,-107.610298
266° W



1/25/24
+37.239140,-107.602885
226° SW

Photo 1. View of the disturbance from the entrance facing center.

Inspection Photos
Location Name: Paisley 2
Location ID: 326675



Photo 2. View of western interim reclamation area facing northeast.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Paisley 2
Location ID: 326675



Photo 3. View of woody and plastic debris observed around active equipment.

Inspection Photos
Location Name: Paisley 2
Location ID: 326675



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Stained soil CA from previous inspection has been addressed.

API #: 067-08675