

Final Reclamation Inspection

January 25th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306890

Inspection Document #: 714000353

La Plata County, CO

Township: SWNE 2 34N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Dwight Sossaman A 2
Location ID: 306890

1/25/24
+37.246797,-107.603392
139° SE



Photo 1. View of the disturbance from the entrance facing center.



API #: 067-08982

Inspection Photos
Location Name: Dwight Sossaman A 2
Location ID: 306890



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Stained material CA from previous inspection has been addressed/resolved.

API #: 067-08982

Inspection Photos
Location Name: Dwight Sossaman A 2
Location ID: 306890



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of musk thistle observed in the northern interim reclamation area.

API #: 067-08982