

Final Reclamation Inspection

January 25th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326618

Inspection Document #: 714000354

La Plata County, CO

Township: SESW 1 34N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Neva Dove 2
Location ID: 326618

1/25/24
+37.239266,-107.590934
285° W



Photo 1. View of the disturbance from the entrance facing center.



Inspection Photos
Location Name: Neva Dove 2
Location ID: 326618



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Russian olive CA from previous inspection has been addressed/resolved.

API #: 067-08412

Inspection Photos
Location Name: Neva Dove 2
Location ID: 326618



1/25/24
+37.239211,-107.591282
244° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of weedy kochia debris lining the southern fence.

API #: 067-08412