

# Inspection Photos

1/25/2024

**Operator:** UTAH GAS OP LTD DBA UTAH GAS  
CORP #10539

**Location ID:** 322479

**Inspection Doc:** 696205578

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location ID: 322479



January 25, 2024



January 25, 2024

**Photo 1:** Photos 1-2 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east. All production equipment has been removed from the Location. Final Reclamation is “in process”.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location ID: 322479



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location ID: 322479



**Photo 3:** Photos taken from the southwest of the Location, facing north. Photos examples showing fill slopes; reclamation work including, but not limited to recontouring/regrading of the cut and fill slopes, compaction alleviation and revegetation activities remain outstanding.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources