

Inspection Photos  
Location Name: SUTTON HH\_22-10J  
Location ID: 320532320532



Photo #1 Crude tank.




Photo #2 P/W vault.



Inspection Photos  
Location Name: SUTTON HH\_22-10J  
Location ID: 320532320532



**Photo #3 Separator.**




**Photo #4 RTU & Meter.**



# Inspection Photos

Location Name: SUTTON HH\_22-10J  
Location ID: 320532320532



Station #	Ad	Gr	Station Name	Sec	TwnShip	Range
04600613653			Sutton HH 22-10-J	22	1S	65W
Radio #	119-0428		Producer Name	Mtr Tube Size		3.066
			Extraction	County		Adams
Transmitter / Module #	Federal #	State #	State		Colo	
16332490						
Static / Span	Up / Dwn	Diff / Span	Temp / Span	Absolute	API #	
0-300	up	0-250	0-150	12.2		
Test Date	OP Size	Beta	Sample Date	H <sub>2</sub> S	Sample Date	H <sub>2</sub> S
9-24-15	1.250		9-24-15	2.0		
9-18-16	1.250		9-18-16	2.5		
9-28-16	1.250		9-28-16	2.5		
3-28-17	1.250		3-28-17	2.0		
9-22-17	1.250		9-22-17	1.5		
3-8-18	1.250		3-8-18	1.5		
9-20-18	1.250		9-20-18	1.5		
9-16-20	1.25		UPGA	-		
9-9-21	1.25		UPGA	-		
9-6-22	1.25		UPGA	-		
9-15-23	1.25		UPGA	-		

Jan 26, 2024 at 1:10:28 PM  
N 39° 56' 54", W 104° 38' 53"  
328° NV  
Adams County Inspection

Photo #5 Meter calibration card.



Photo #6 Well head.