Attachment B

TASMAN GEOSCIENCES

SITE NAME: STROHAUER F 33-32D WELLHEAD		**DATE:** 1/9/2024	**REM. PROJECT #:** 32333	**WEATHER:** 40S SUNNY
SITE DIRECTIONS: CR 50 & W CR 41, N 0.25 MILES THEN W 0.25 MILES INTO SITE		**CLIENT:** PDC		
LEGALS AND LAT/LONG: 40.353862, -104.679946		**TASMAN PERSONNEL:** JH		
SOIL TYPES: Well Graded Sand - SW		**SURFACE GRADIENT:** Southwest		

SOIL SAMPLING

Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?
1/9/2024 12:00	WH01 @ 6'	0.0	No Staining	No Odor	Yes	Lab
1/9/2024 12:05	FLR01 @ 4'	0.4	No Staining	No Odor	Yes	Lab
1/9/2024 12:10	WHS01-N @ 0-6"	0.0	No Staining	No Odor	Yes	Grab
1/9/2024 12:15	WHS01-W @ 0-6"	0.0	No Staining	No Odor	Yes	Grab
1/9/2024 12:20	WHS01-S @ 0-6"	0.0	No Staining	No Odor	Yes	Grab
1/9/2024 12:25	WHS01-E @ 0-6"	0.0	No Staining	No Odor	Yes	Grab
1/9/2024 12:30	BKG01 @ 4'	0.1	No Staining	No Odor	Yes	Lab
1/9/2024 12:35	BKG01 @ 5'	0.1	No Staining	No Odor	Yes	Lab
1/9/2024 12:40	BKG01 @ 6'	0.1	No Staining	No Odor	Yes	Lab
1/9/2024 12:45	BKG02 @ 4'	0.0	No Staining	No Odor	Yes	Lab
1/9/2024 12:50	BKG02 @ 5'	0.0	No Staining	No Odor	Yes	Lab
1/9/2024 12:55	BKG02 @ 6'	0.0	No Staining	No Odor	Yes	Lab
1/11/2024 09:09	FL01-01 @ 4'	0.0	No Staining	No Odor	Yes	Grab
1/11/2024 09:20	FL01-02 @ 4'	0.0	No Staining	No Odor	Yes	Lab
1/11/2024 09:25	FL01-03 @ 4'	0.0	No Staining	No Odor	Yes	Grab
1/11/2024 09:30	FL01-04 @ 4'	0.0	No Staining	No Odor	Yes	Lab
1/11/2024 11:40	FL01-05 @ 4'	0.0	No Staining	No Odor	Yes	Lab
1/11/2024 10:30	FL01-06 @ 4'	0.1	No Staining	No Odor	Yes	Lab
1/11/2024 10:40	FLR02 @ 4'	0.1	No Staining	No Odor	Yes	Lab

GROUNDWATER SAMPLING

Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?

FACILITY INFRASTRUCTURE

EQUIPMENT	Quantity
Above Ground Storage Tank (AST)	
Buried or Partially Buried Vessel	
Separator	
Emission Control Device (ECD)	
Dump Line	
Wellhead	1
Flowline	1
Other:	

Soil Loads Removed

IMPACTED SOIL IDENTIFIED?

ESTIMATED VOLUME OF IMPACTS:

Date	Number	CY
Total Removed	0	0

Disposal Facility:

Groundwater Recovery

DATE GW ENCOUNTERED: | DEPTH:

GROUNDWATER IN CONTACT WITH IMPACTED SOIL?

LNAPL OR SHEEN OBSERVED ON GW?

Date	BBLS
Total Removed	0

Disposal Facility:

GENERAL OBSERVATION FORM

Client: PDC

Site Area/AOC: Strohauer F 33-32D Wellhead Date: 1/10/2024

Task/Location Description: Wellhead Decommissioning & Confirmation Sampling

Daily Forecast/Weather: 40s sunny Personnel: JH

Description of Activities:

Time	Description
11:00	PACM was encountered at FL01-01, crew was instructed to stop potholing along the flowline until we have confirmation that
	the suspect coating isn't asbestos
08:30	Received confirmation from lab that the line did not contain asbestos
10:00	During flowline decommissioning the crew hit an unmarked water line and a stop work was called
10:30	received permission to return to work
11:30	A water truck was called to site, and the sample FL01-05 was able to be collected

TASMAN GEOSCIENCES

Photographic Log

Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:
Notes/Conditions: WH01-S		

Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:
Notes/Conditions: WH01-E		

TASMAN GEOSCIENCES

Photographic Log

Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:
Notes/Conditions: WHS01-N		

Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:
Notes/Conditions: WHS01-W		

TASMAN GEOSCIENCES

Photographic Log

Equipment ID:	Equipment Type:		Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions: WHS01-S			Notes/Conditions: WHS01-E		

TASMAN GEOSCIENCES

Photographic Log

Equipment ID:	Equipment Type:		Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions: BKG01			Notes/Conditions: BKG02		

TASMAN GEOSCIENCES

Photographic Log

Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:
Notes/Conditions: FL01-01		

Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:
Notes/Conditions: FL01-02		

TASMAN GEOSCIENCES

Photographic Log

Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:
Notes/Conditions: FL01-03		

Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:
Notes/Conditions: FL01-04		

TASMAN GEOSCIENCES

Photographic Log

Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:
Notes/Conditions: FL01-06		

Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:
Notes/Conditions: FLR02		

TASMAN GEOSCIENCES

Photographic Log

Equipment ID:	Equipment Type:		Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:	Material:	Volume:	Contents:
Notes/Conditions:			Notes/Conditions: FL01-05		