

Inspection Photos
Jillson #2 Bullplug Hist. Release
Spill ID 485797



Photo 1 – Spill area.



Photo 2 - Open excavation.



Inspection Photos
Jillson #2 Bullplug Hist. Release
Spill ID 485797



Photo 3 – Stockpile.



Photo 4 - Stockpile.

Inspection Photos
Jillson #2 Bullplug Hist. Release
Spill ID 485797



Photo 5 – Stockpile.



Photo 6 - Stockpile.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources